NM OIL CONSERVATION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

> Oil Conservation Division 1220 South St. Francis Dr.

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

SEP 16 2015 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

1220 S. St. Fran	icis Dr., Sant	a re, NM 8750:)	Sa	anta F	e, NM 875	505						
		The same of the same of	Rele	ease Notific	catio	n and Co	orrective A	ction					
NAB15	26539	130/	OPERATOR					Г	Final Repo				
Name of C	ompany D	Devon Energy	Contact Rudy Zuniga										
Address 6488 Seven Rivers Hwy Artesia, NM 88220						Telephone No. 575-390-5435							
Facility Na	me Hackb	erry 18 Fed	1			Facility Ty	pe Oil						
Surface Owner Federal Mineral Owner							r Federal API No. 30-015-29780						
				LOC	TIO	N OF RE	EASE						
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/West Line		County		····	
0	18	198	31E	660	,	South	1980	East		Eddy			
<u> </u>	L	L			l					<u> </u>			
		I	.atitude:	N 32'65'49.53'	,	Loi	igitude: W 103	3190165.32	•				
				NAT	URE	OF RELI	EASE						
Type of Release Spill						Volume of Release Volume Recovered							
Oil and Produced water Source of Release										nd 68 produced water d Hour of Discovery			
2 phase separator on the Sirius 17 Fed 3 overflowed into the tank										5@ 9:30 am			
Was Immediate Notice Given?						If YES, To Whom?							
☐ Yes ☐ No ☐ Not Required						BLM Jim Amos OCD Mike Bratcher							
By Whom?						Date and Hour							
Lynn Smith						9/14/2015 4:03 pm							
Was a Watercourse Reached?						9/15/2015 7:40 am If YES, Volume Impacting the Watercourse							
Yas a Watercourse Reaction: Yes No													
If a Waterco	urse was Ii	mpacted, Des	cribe Full	v.*		L							
Describe Car					ad Lone	I noticed the t	anks were overflo	uning The C) mbaaa	. compressor of	b.a. (Simina 17 Ead	
							bls of oil and 70 t						
				cover 397 bbls of				•					
<u> </u>	1.00 1.7	1.67	A 41 77										
Describe Are The spill affect				aken.* ne cleanup for the	remaine	ed of the 5 bb	ls.						
p													
I haraby cartif	Fy that the is	formation air	ian aharia	is true and sampl	ata to th	a hast of my l	cnowledge and un	dangton d the		iont to NIMC	OCD.		
							d perform correct						
public health	or the envir	onment. The	acceptance	of a C-141 repor	t by the	NMOCD ma	rked as "Final Re	port" does n	ot relie	eve the opera	ator o	f liability	
should their o	perations ha	ave failed to a	dequately i	investigate and re	mediate	contaminatio	n that pose a thre	at to ground	water,	surface wat	er, hı	ıman health	
federal, state,	or local law	s and/or regul	ations.	ance of a C-141 i	eport do	es not reneve	the operator of re	esponsibility	ior co	mphance w	th an	y otner	
- marchine	Company of the Compan	THE PROPERTY	n alter legende manger	THE PERSON NAMED AND POST OF THE PERSON	t and the face	Ну г	OIL CONS	ERVAT	ON :	DIVISIO	\overline{N}^-		
Signature: Corina Moya								1 1	1				
Drinted Name: Cavina Mati-						Approved by Environmental Specialist							
Printed Name: Corina Moya A							Approved by Environmental Specialist:						
Title: Field A	dmin Supp	ort				pproval Date	1122/15	Expira	ation E	oate: N/A	t		
						andition of A							
L-man Audies	o. Comail	avya w uvnach	····			onumons of	rappiovai:	dec 8. Gu	idalir	Attached			
	16/2015		one: 575. 7	46.5559	Re	mediation	per O.C.D. Ru	TIES & GN	_NU		5° € 25	g aktas saata en	
Attach Additi	ional Sheet	ts If Necessa	ry		SU	BMIL HEL	HEDIATION P	16		-	200	2000	

LATER THAN:___