

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 17 2015  
Form C-141  
Revised August 8, 2011  
  
Submitted to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1526458218**

**OPERATOR**

☒ Initial Report    ☒ Final Report

Name of Company: COG Operating LLC <b>229137</b>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Dirty Dozen Federal Com #4H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-38150
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	19S	31E	1650'	South	660'	East	Eddy

Latitude 32.614254 Longitude -103.8162079

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 12 bbls PW	Volume Recovered: 10 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 8/31/2015 7:00 am	Date and Hour of Discovery: 8/31/2015 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by corroded flowline in the battery piping. A vacuum truck was dispatched to recover all standing fluid and repairs were made.

Describe Area Affected and Cleanup Action Taken.

This release was contained within a lined facility. The facility was cleaned, repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: <b>9/22/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: September 14, 2015    Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

**2RP-3277**