

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 16 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1526432988

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>166696</i>	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Federal 23 #13H	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-41636
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	26	22S	31E					Eddy County, NM

Latitude N 32.36785° Longitude W 103.75581°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10 bbls oil, 10 bbls produced water	Volume Recovered	60 bbls, including approx.. 40 bbls of rain water
Source of Release	Stress/fatigue of a 4" poly production line	Date and Hour of Occurrence	08/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/25/2015 @ 2:35 pm	<i>Rel. 10 bbls oil 10 bbls PW</i>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted; Describe Fully.*

*REC: 9 bbls oil
9 bbls PW*

Describe Cause of Problem and Remedial Action Taken.*

Stress/fatigue of a 4" poly line caused 10 bbls of oil and 10 bbls of produced water onto the ground. The line was repaired and a vacuum truck recovered 60 bbls of fluids, including approximately 40 bbls of rain water.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 30' on location. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: CJ Summers	Approved by Environmental Specialist: 	
Title: HES Lead	Approval Date: <i>9/11/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: chancy summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>9-11-15</i> Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/22/15

2RP- 3269