

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526633315

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Linn Operating Inc. 264324	Contact	E.L. Gonzales
Address	2130 W Bender Blvd Hobbs, NM- 88240	Telephone No.	575-738-1739
Facility Name	Turner A Battery (closest well Turner A #58)	Facility Type	Battery
Surface Owner	Federal	Mineral Owner	
		API No. closest well	30-015-29001

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	18	17S	31E	560	South	1880	East	Eddy

Latitude 32.8288116 Longitude -103.9066696

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	52 bbls	Volume Recovered	50 bbls
Source of Release	Pump	Date and Hour of Occurrence	09/14/2015	Date and Hour of Discovery	09/14/2015 10:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

NM OIL CONSERVATION
ARTESIA DISTRICT

SEP 18 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.* Drove up to gauge up battery and do daily inspection and noticed water inside dike. Walked around to transfer pump noticed pump running but not moving no fluid. Love joy coupling had busted. Causing for both water tanks to fill up. Never got a call out from alarm for high tank levels.

Describe Area Affected and Cleanup Action Taken.* Affected Area is 45'X30'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: E.L. Gonzales

Title: Production Supervisor

E-mail Address: elgonzales@linenergy.com

Date: 09/17/2015

Phone: 505-504-8002

Approved by Environmental Specialist:

Approval Date: 9/23/15

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO

Attached ☐

LATER THAN: 10/25/15

2RP-3284

* Attach Additional Sheets If Necessary