

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 21 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526650929

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Quail BQL State Com #1H		Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-38170
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter O	Section 2	Township 26S	Range 30E	Feet from the 330	North/South Line South	Feet from the 1650	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.06531 Longitude 103.84832

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 16 B/PW	Volume Recovered 16 B/PW
Source of Release Production Tank	Date and Hour of Occurrence 8/27/2015; AM	Date and Hour of Discovery 8/27/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The water leg on the production tank was knocked down by the wind, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 35'X 18' within the lined/bermed battery. The valves were closed and all of the produced water was recovered (100%). Depth to Ground Water: > 100' (approximately 250', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on all released produced water recovered and the battery being lined and bermed, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Asher		Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor		Approval Date: 9/23/15	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: September 21, 2015	Phone: 575-748-4217	2RP-	

* Attach Additional Sheets If Necessary

2RP-3289