Office NM OIL CONSERVATION	Form C-103
Office NM OIL CONSERVATION Minerals and Natural Resources District I – (575) 393-6161 ARTESIA DISTRICT 1625 N. French Dr., Hobbs, NM 88240 District II. (575) 748 1383 ALIC O. 4 2045	Revised July 18, 2013 WELL API NO.
	30-015-03206
District II - (575) 748-1283 AUG 2.4 2015 IL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 RECEIVED Santa Fe, NM 87505	STATE 🔀 FEE 🗌
	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-7640
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Old Loco Unit
1. Type of Well: Oil Well Gas Well X Other Injection	8. Well Number 005
2. Name of Operator Tandem Energy Corporation	9. OGRID Number 236183
3. Address of Operator	10. Pool name or Wildcat
2700 Post Oak Blvd. Ste. 1000, Houston, TX 77056	Grayburg - Jackson
4. Well Location	200
	get from the West line
Section 32 Township 17S Range 29E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB
DOWNHOLE COMMINGLE CLOSED LOOP SYSTEM	
CLOSED-LOOP SYSTEM OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
Pulled tubing and nacker out of the well. The nacker had sheared and was incanable of setting	α.
Pulled tubing and packer out of the well. The packer had sheared and was incapable of setting. Ran a 7" 20-23# retrievable bridge plug and set the RBP at 2443' the original packer setting depth.	
Tested the production casing to 500 psi.	
Lost 15 psi in 30 minutes. Pulled out RBP	
Ran a 7" 20-23# Tension set packer and 2-3/8" 4.7# EU IPC tubing to 2443',	
set the packer and pulled 19,000 lbs tension on the tubing and packer. Tested the casing to 500 psi and lost 20 psi in 30 minutes.	
Patched slow casing leak with Enviro Plug	
R/U Nitrogen Treating/Pressure Manifold to wellhead. Pour one container of Enviro Plug down the tubing casing annulus.	
Set the pressure regulator to 500 psi and maintain 500 psi during treating operation.	
MIT was conducted on 8/6/2015 and was chart recorded and witnessed by OCD representative. Place the well back on injection and report injection volumes, injection and casing pressures re-	
	•
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Thereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE Regulatory Spec	cialist DATE 08/11/2015
Type or print name L. Kiki Lockett E-mail address: kikil@t5en	ergy.com PHONE: 713-987-7326
APPROVED BY: Ruther TITLE COMPLIANUS OF Conditions of Approval (if any):	PULL DATE 9/24/15