



MERIT ENERGY COMPANY

P.O. Box 300, Whiteface, TX 79379 806-229-6300 phone 806-229-2583 fax

30-015-05191

November 9, 2005

Chris Beadle, Inspector
New Mexico Energy, Minerals and
Natural Resources Department
Oil Conservation Division
1301 West Grand Ave.
Artesia, NM 88210

RECEIVED
NOV 10 2005
OGD-ARTESIA

CERTIFIED MAIL 70023150000396583936

Dear Mr. Beadle:

This letter is in reference to routine inspection violations on the following wells:

Turner B 40 Inspection Date 10/27/2005 Inspection Number iCLB0530037522
Turner B 37 Inspection Date 10/27/2005 Inspection Number iCLB0530037039
Turner B 32 Inspection Date 10/27/2005 Inspection Number iCLB0530036576

These three well violations have been corrected by placement of new well signs with proper operator identification.

Thank you,

Kari High
Merit Energy Company
New Mexico Field Office
Administrative Assistant

40: 30-015-05194
37: 30-015-05193
32: 30-015-05191