Form 3150-5 (August 1999)

# UNITED STATES DEPARTMENT OF THE INTERIOR 201 W. Grand Ave

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

BUREAU OF LAND MANAGEMENT 1301 W. Grand Avenue

Chase Serial No. NMNM106832X SUNDRY NOTICES AND REPORTS ON WALLSSIA, NM 882 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on reverse side If Unit or CA/Agreement, Name and/or No. NMNM106832X Type of Well West High Lonesome Unit Oil Well Gas Well Dother Waterflood Unit 8. Well Name and No. WHLPSU 2. Name of Operator BEACH EXPLORATION, INC API Well No. 3a. Address 3b. Phone No linclude a 30-*01*5 800 N. MARIENFELD, STE 200, MIDLAND, TX 915-683-6226 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) High Lonesome Oueen Sections 2/17-16-S, R-29-E County or Parish, State Eddy County, New Mexico 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off Notice of Intent ☐ Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair ■ New Construction Subsequent Report Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back ☐ Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene 5/22/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1690'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining. 7/23/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 50 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1581.82'. Loaded backside of packer w/25bbls packer fluid, set packer w/26 pts, pressure tested backside. Tested OK. RD 7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

See attached pages 2 & 3

TA The Land Control of the Control o		FOR DECORD	
<ol> <li>I hereby certify that the foregoing is true and correct Name (Printed/Typed)</li> </ol>	1	ACCEPTED FOR REGURD	==
Lizbeth Lodle	Title Engin. Analys	t	
Signature Suluth Godle	Date June 13, 2003	JUN 2 4 2003	
THIS SPACE FOR FEDER	AL OR STATE OFFICE I	IERRARYAK I	
Approved by	Title	PETROLEUM ENGINEER Date	
Conditions of approval, it has, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	rant or t lease Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for a States any false rictitious or fraudulent statements or representations as to any matter.	my person knowingly and willi	fully to make to any department or agency of the Unite	= :d

#### WHLPSU 3

5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene

5/24/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1784'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/22/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 52 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1643.84'. Loaded backside of packer w/22bbls packer fluid, set packer w/24 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

#### WHLPSU 5

5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene

5/24/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. Tbg stuck.

5/28/02 Ran free-point. Tog free at 1790' (PBTD 1840', bottom perf 1764'). Chem cut tbg at 1788' RIH w/bit and scraper. Clean out to 1788'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/19/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 54 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1649.20'. Loaded backside of packer w/22bbls packer fluid, set packer w/24 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

### WHLPSU 7

5/21/02 Treated down 2 3/8" x 5 1/2" annulus w/250gal xylene

5/22/02 Stacked rods out. Loaded and press tested the to 2500psi. Layed down rods and pump. POOH w/the RIH w/bit and scraper. Clean out to 1660'. POOH. RIH w/the and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down the Sent the to Rice Engineering for Duo-10 lining.

7/22/02 RIH w/5 1/2" 17-20# PC AD-1 pkr, PC seating nipple, 48 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of pkr @ 1505.54'. Loaded backside of packer w/40bbls packer fluid, set packer w/28 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

### WHLPSU 13

5/21/02 Treated down 2 3/8" x 7" annulus w/250gal xylene

5/24/02 Stacked rods out. Loaded and press tested the to 2500psi. Pump stuck. Layed down rods.

5/28/02 POOH w/tbg. RIH w/bit and scraper. Clean out to 1760'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laid down tbg. Sent tbg to Rice Eng for Duo-10 lining

7/15/02 RIH w/7" PC AD-1 packer, PC seating nipple, 49 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1538.64'. Loaded backside of packer w/65bbls packer fluid, set packer, pressure tested backside Tested OK. RD

7/25/02 OCD conducted injection well integrity test. Well did not pass. Shallow csg leak.

8/9/02 RU Re-Entry People release pkr. POOH w/tbg. Dumped and washed 38.1 cuft of masonary sand down csg. Welded 8 5/8" csg to 7" csg. Cut 7" csg off and welded 7" 8rd nipple to 7" csg. SDFN

8/12/02 RIH w/tbg, tagged sand @ 1675', washed sand to 1760'. Circulated 1/2 hr. POOH; RIH w/55 jts 5 1/2"
15.5# LT & C D &T csg set csg @ 1757'. Insert Float @ 1725'. Weld on 5 1/2" x 7" bell nipple. RU FCI, mixed and pumped 135 sxs C neat cmt w/2% CaCl. Displaced w/42 bbls of water, bumped plug at 5:51 pm w/620 psi. Cement circulated to surface. SI SDFN.

8/13/02 RIH w/4 3/4" bit. Drld insert float at 1725'. Drld cmt 1725' to 1760'. Wahed sand from 1760' to 1805'. Drld hard fill from 1805 to 1815'. Circ hole 3/4 hr. POOH. RIH w/5 1/2" PC AD-1 packer, PC SN, and 54 jts of 2 3/8" J55 4.7# Duo-10 lined tbg. Bot of packer at 1689'. Pumped 38 bbl packer fluid down annulus. Set packer w/28 pts. Test backside to 500 psi. OK. Test pumped down injection tbg at 2 BPM (2880 BWPD) at 700psi. SI RD.

8/27/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

# WHLPSU 14

5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene

5/22/02 Loaded and press tested the to 2500psi. POOH w/the RIH w/bit and scraper. Clean out to 1760'. POOH. RIH w/the and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down the Sent the to Rice Engineering for Duo-10 lining.

7/19/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 53 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1649.20'. Loaded backside of packer w/22bbls packer fluid, set packer w/18 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

### WHLPSU 15

5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene

5/23/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1798'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/18/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 53 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1648.44'. Loaded backside of packer w/22bbls packer fluid, set packer w/18 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

#### WHLPSU 17

5/21/02 Treated down 2 3/8" x 5 1/2" annulus w/250gal xylene

5/24/02 Stacked rods out. Loaded and press tested tog to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1761'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/17/02 RIH w/5 1/2" PC AD-1 packer, PC seating nipple, 52 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1636.33'. Loaded backside of packer w/36bbls packer fluid, set packer w/26 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

5/21/02 Treated down 2 3/8" x 4 1/2" annulus w/250gal xylene

5/23/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1825'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/17/02 RIH w/4 1/2" PC AD-1 packer, PC seating nipple, 53 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1704.01'. Loaded backside of packer w/18bbls packer fluid, set packer w/24 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

# WHLPSU 23

5/21/02 Treated down 2 3/8" x 7" annulus w/250gal xylene

5/24/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg RIH w/bit and scraper. Clean out to 1548'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/16/02 RIH w/7" PC AD-1 packer, PC seating nipple, 49 jts 2 3/8" J-55 Duo-10 lined tbg. Backside would not load. Isolated 7" csg leak between 258' and 320'. POOH. Laid down PC tbg. RD

8/5/02 RU Re-Entry People. Dumped 51.2 cubic ft mortar sand, break off old wellhead. Weld 7" 8rd nipple to 7" csg collar above

8/6/02 Installed Figure 92 7" csg head. RIH w/57 jts tbg, tagged sand @ 1789'. Dumped 146 cubic ft in well. Tagged sand @ 1695'. POOH. Fluid now standing 225' from surface. Dumped 32 cubic ft. sand in well. Total sand in well 230 cubic ft. SDFN

8/7/02 RIH w/44 jts 5 1/2" 17# J-55 LT&C D&T csg set @ 1691'. Insert float @ 1648'. RU FCI Cementers. Pumped 125 sx C neat w/ 2% CaCl. Dropped plug and displaced w/40 bbls fresh water. Bumped plug w/620 psi. Had circ during entire job. Cmt circulated to surface. SI SDFN

8/8/02 RIH w/ 4 3/4" bit and tbg. Drld float at 1650'. Drld cmt to 1695' and into sand. Circ sand out to 1821'. Circ for 3 hrs. POOH laying down tbg. RIH w/ 5 1/2" PC AD-1 packer, PC SN, and 52 jts of 2 3/8" J55 Duo-10 lined tbg. Bot of packer at 1640.25'. SI SDFN

8/9/02 Pumped 36 bbl pkr fluid down annulus. Set packer w/26 pts. Press up on backside - OK. RU to tbg and test pumped 1 BPM at 600 psi (1440 BWPD) SI RD

8/27/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

## WHLPSU 25

5/21/02 Treated down 2 3/8" x 5 1/2" annulus w/250gal xylene

5/23/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg
RIH w/bit and scraper. Clean out to 1832'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15% NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.

7/18/02 RIH w/5 1/2" PC AD-1 packer, PC seating nipple, 54 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer @ 1713.78'. Loaded backside of packer w/36bbls packer fluid, set packer w/24 pts, pressure tested backside. Tested OK. RD

7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)

WHLPSU 27

5/21/02 Treated down 2 3/8" x 5 1/2" annulus w/250gal xylene

5/23/02 Stacked rods out. Loaded and press tested tbg to 2500psi. Layed down rods and pump. POOH w/tbg
RIH w/bit and scraper. Clean out to 1816'. POOH. RIH w/tbg and pkr. Set pkr, acidized w/300gal 15%
NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo. 10 lining.

NEFE acid. Well on vacuum. POOH. Laying down tbg. Sent tbg to Rice Engineering for Duo-10 lining.
7/17/02 RIH w/5 1/2" PC AD-1 packer, PC seating nipple, 53 jts 2 3/8" J-55 Duo-10 lined tbg. Bottom of packer
@ 1712.66'. Loaded backside of packer w/packer fluid, attempted to pressure test backside; well head rubbers not sealing. Will replace Thursday & test. RD

7/18/02 Unflange wellhead, install new pack-off plate & rubber. Flanged up wellhead. Test backside. Tested Ok 7/26/02 OCD conducted injection well integrity test. Well passed (chart at OCD in Artesia)