

2/17/2006

Wellbore Diagram

r263

30-015-34326-00-00

SKELLY UNIT No. 960

Company Name: CHEVRON U S A INC

Location: Sec: 14 T: 17S R: 31E Spot:

Lat: Long:

Property Name: SKELLY UNIT

County Name: Eddy

String Information

Cement Information

Perforation Information

Top (ft sub)	Bottom (ft sub)	Shts/Ft	No Shts	Dt Sqz
0	0			

Formation Information

St Code	Formation	Depth
Prust	Rustler	508
Psal	Salado	726
Pbslt	Base of Salt	1699
Pyts	Yates	1854
Psr	Seven Rivers	2184
Psrbs	Bowers Sand	2578
Pqu	Queen	2802
Psa	San Andres	3544
Pgl	Glorieta	5056

Hole: Unknown

TD:

TVD: 0

PBTD: