

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1528634487 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <u>6137</u>	Contact Leonard Aguilar
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.1930
Facility Name Pure Gold C-17 Federal 4	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-27153
-----------------------	-----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	23S	31E	1780	FNL	330	FEL	Eddy

Latitude: 32.306709 Longitude: -103.791939

**NATURE OF RELEASE**

Type of Release Spill OIL	Volume of Release 200 BBL	Volume Recovered 185 BBL
Source of Release Water dump clogged and sent oil to oil tank	Date and Hour of Occurrence 10/08/15 at 10:30am	Date and Hour of Discovery 10/08/15 at 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos-BLM Mike Bratcher-OCD	
By Whom? Leonard Aguilar	Date and Hour 10/08/15 7:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
OCT 12 2015  
**RECEIVED**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Water pump clogged and sent all production to the oil tank, the tank ran over. The lease operator shut in wells, switched tanks and drained heater.

Describe Area Affected and Cleanup Action Taken.\*  
200 BBL of oil was released all in containment and 185 BBL of oil recovered from containment. With an over spray of .5 BBL of oil that sprayed off pad onto the southwest corner a 20 X 50 foot area. An environmental company will be called out to evaluate the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jeanette Barron</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <u>Jeanette Barron</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>10/13/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Jeanette.barron@dv.com</u>	Conditions of Approval:	
Date: <u>10/12/15</u> Phone: <u>575.748.1813</u>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO. <u>2RP-3324</u>	

\* Attach Additional Sheets If Necessary

LATER THAN: 11/13/15