

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**0AB1529339864** **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company Burnett Oil Co., Inc <b>3080</b>	Contact Leslie Garvis
Address 801 Cherry Street, Ste 1500, Fort Worth, Texas 76102	Telephone No. 817-583-8730
Facility Name Gissler A 42	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-40846
-------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	12	17S	30E	990	South	230	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Oil	Volume of Release 3 bbls	Volume Recovered 0 bbls
Source of Release Oil Tank	Date and Hour of Occurrence 10/12/15	Date and Hour of Discovery 10/12/15 0937
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Note: BLM called Burnett about this release before Burnett had chance to report it.	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

NM OIL CONSERVATION  
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.\*  
Packing leaked from the well head. Repaired

OCT 16 2015



RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Released covered 3'x50' on pad and 6'x100' in adjacent pasture. Area on pad will be scraped. Area in pasture will be sampled and blended with a tiller to minimize impact on surrounding vegetation. Burnett (J. Titworth) discussed the plan to clean up the pasture with both the BLM and the OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Leslie Garvis	Approval Date: 10/20/15	Expiration Date: N/A
Title: Regulatory Coordinator	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
E-mail Address: lgarvis@burnettoil.com		
Date: 10/16/15 Phone: 817-583-8730		

\* Attach Additional Sheets If Necessary

2RP 3344