

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Pat Ellis</b>
Address <b>550 W. Texas, Suite 1300 Midland, Texas 79701</b>	Telephone No. <b>(432) 685-4332</b>
Facility Name <b>Muskegon 16 State Com #1</b>	Facility Type <b>Tank Battery</b>

Surface Owner: <b>State</b>	Mineral Owner	Lease No. <b>API # 30-015-27108</b>
-----------------------------	---------------	-------------------------------------

**LOCATION OF RELEASE**

Unit Letter <b>N</b>	Section <b>16</b>	Township <b>17S</b>	Range <b>29E</b>	Feet from the <b>660</b>	North/South Line <b>S</b>	Feet from the <b>1980</b>	East/West Line <b>W</b>	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	------------------------------	------------------------------	----------------------------	-----------------------

Latitude N 32.82888° Longitude W 104.08204°

**NATURE OF RELEASE**

Type of Release: <b>Oil and Produced Water</b>	Volume of Release <b>50 bbls</b>	Volume Recovered <b>35 bbls</b>
Source of Release: <b>Tank</b>	Date and Hour of Occurrence <b>10/28/09 1:16 p.m.</b>	Date and Hour of Discovery <b>10/28/09 1:16 p.m.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <b>Rick Wright</b>	Date and Hour <b>10/28/09 2:43 p.m.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

The tank overflowed due to a pump malfunction.

Describe Area Affected and Cleanup Action Taken.\*

The release stayed on the pad and entrance road. Tetra Tech inspected site and collected samples to define spills extent. An approved work plan was prepared and implemented. Removed soil was hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Ike Tavarez</b>		Approved by District Supervisor: 	
Title: <b>Senior Project Manager</b>		Approval Date: <b>10/6/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>Ike.Tavarez@TetraTech.com</b>		Conditions of Approval: <b>Final</b>	Attached <input type="checkbox"/>
Date:	Phone: <b>(432) 682-4559</b>		

\* Attach Additional Sheets If Necessary

22P-433