

AUG 11 2009

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-28659

Release Notification and Corrective Action

nMLB 092874938

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ExxonMobil	7673	Contact Toni Collier
Address P.O. Box 4358, Houston, TX 77210		Telephone No. 281-654-1133
Facility Name Avalon Delaware Unit #238		Facility Type Injection line
Surface Owner State Of New Mexico	Mineral Owner	Lease No. API#3001528659

LOCATION OF RELEASE

Unit Letter K	Section 30	Township 20S	Range 28E	Feet from the 2301	South Line	Feet from the 1485	West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------	-----------------------	-----------	----------------

Latitude 32 32.641 Longitude 104 13.243

NATURE OF RELEASE

Type of Release :Produced Water	Volume of Release 83 bbls of produced water	Volume 0 bbls
Source of Release 3" Fiberglass injection line	Date and Hour of Occurrence	Date and Hour of Discovery 7/28/09 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Artesia Office Answering Machine-Mike Bratcher	
By Whom? Shelby Pennington	Date and Hour 7/28/09 4:15	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* No watercourse in area



Describe Cause of Problem and Remedial Action Taken.*

3" Fiberglass line developed leak. Leak was isolated and repaired. Emergency crew was sent to site to begin remediation

Describe Area Affected and Cleanup Action Taken.*

Area covered approx. 7,000 square foot. Emergency crew was sent to site to begin excavation of highly saturated soil. Site will be delineated and a remediation plan will be submitted for approval to the NMOCD Artesia office.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kevin M. Dillow	Approved by 	
Title: Compliance Supervisor	Approval Date: OCT 14 2009	Expiration Date:
E-mail Address: Kevin.m.dillow@exxonmobil.com	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 10/14/09 Remediation in progress	
Date:	Phone: 281-654-1557	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

PMLB 0928750680