

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1529538052

155615

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Nadel and Gussman Permian, LLC	Contact: Bill Dougherty
Address: 601 N. Marienfeld, Suite 508, Midland, TX 79707	Telephone No. 325-998-7107
Facility Name: South Taylor 13 Federal #5	Facility Type: Oil Well

Surface Owner U.S.A	Mineral Owner	API No. 30-015-37092
---------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter J	Section 13	Township 18 S	Range 31 E	Feet from the 1697	North/South Line SOUTH	Feet from the 1600	East/West Line EAST	County EDDY
------------------	---------------	------------------	---------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil and Water	Volume of Release 26 BBLS	Volume Recovered 24 BBLS
Source of Release Leaking Firetube Gasket	Date and Hour of Occurrence 10/19/2015 Early Morning	Date and Hour of Discovery 10/19/2015 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelley Tucker of the BLM on 10/19/2015 and Heather Patterson of OCD on 10/20/2015	
By Whom? Bill Dougherty	Date and Hour 10/19/2015 10:15 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The firetube gasket on the Heater Treater leaked.  
A Double R Vacuum truck arrived on location 10:15 AM.

Describe Area Affected and Cleanup Action Taken.\*

Approx. 24 BBLS of oil and produced water were released into the separation equipment berm, which borders the location edge. Separation berm is lined with plastic. Approx. 2 BBL of spray and run off got off of location.

A double R vacuum truck sucked up all oil and produced water inside the berm and put back in production tanks.

Contaminated soil will be scraped up and hauled to disposal site (R360), and then NGP will take a sample of the soil where the run off/over-spray occurred. Sample will be sent to Trace Analysis for analysis and sample results will be sent to Shelly Tucker of the BLM. Pending sample results, additional remediation, if any is needed, will be performed. A final C-141 will be submitted with location pictures after all remediation work is finished.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: <u>Sarah Presley</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Printed Name: Sarah Presley	Approval Date: <u>10/22/15</u>	Expiration Date: <u>N/A</u>
Title: Regulatory Analyst	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
E-mail Address: spresley@naguss.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 10/21/2015	Phone: 432-682-4429	

ATER THAN: 11/23/15

2RD-3349

NM OIL CONSERVATION  
ARTESIA DISTRICT

OCT 21 2015

RECEIVED