

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 27 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production		Contact Mike McMahan Production Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.706.4165
Facility Name Shakespeare 20 Fed Com 1H		Facility Type Oil
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-36376

LOCATION OF RELEASE

Unit Letter P	Section 20	Township 16S	Range 28E	Feet from the 400	North/South Line FSL	Feet from the 330	East/West Line FEL	County EDDY
-------------------------	----------------------	------------------------	---------------------	-----------------------------	--------------------------------	-----------------------------	------------------------------	-----------------------

Latitude:

Longitude:

NATURE OF RELEASE

Type of Release Spill Oil & Produced water	Volume of Release 1 BBL oil & 4 BBL produced water	Volume Recovered 1 BBL oil & 3 BBL produced water
Source of Release Stuffing box blow out on pump jack	Date and Hour of Occurrence 10.18.15 at 1:00 pm	Date and Hour of Discovery 10.18.15 at 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher BLM Jim Amos OCD	
By Whom? Mike McMahan	Date and Hour 10.19.15 at 9:45 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Stuffing box blew out on pump jack. Lease operator shut down valve.

Describe Area Affected and Cleanup Action Taken.*

1 BBL of oil and 4 BBL of produced water released. A vacuum truck recovered 1 BBL oil and 3 BBL produced water. All this occurred on location on an 8 x10 area near the wellhead and a 3x10 area near the pump jack. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: **Jeanette Barron**

Printed Name: **Jeanette Barron**

Title: **Field Admin Support**

E-mail Address: **Jeanette.barron@dm.com**

Date: **10.27.15**

Phone: **575.748.1813**

OIL CONSERVATION DIVISION

Signed By **[Signature]**

Approved by Environmental Specialist:

Approval Date: **10/28/15**

Expiration Date: **N/A**

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

11/24/15

2RP-3360

* Attach Additional Sheets If Necessary