

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**NAB1530829829** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <b>0137</b>	Contact Dan Suniga Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.1930
Facility Name Ore Ida 14 Fed 10	Facility Type SWD

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29290
-----------------------	-----------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	24S	29E	1780	FSL	860	FEL	EDDY

Latitude: 32.215079 Longitude: -103.948767

### NATURE OF RELEASE

Type of Release Spill Produced water	Volume of Release 25 BBL	Volume Recovered 0 BBL
Source of Release Hole in 3 inch poly pipe	Date and Hour of Occurrence 10/27/15 at 1:30 PM	Date and Hour of Discovery 10/27/15 at 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos -BLM Mike Bratcher -OCD	
By Whom? Leonard Aguilar	Date and Hour 10/28/15 at 12:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* 3 inch poly pipe ran over creating a hole which resulted in release. Transfer pumps shut off to prevent further release. The poly pipe is scheduled for repair.		
Describe Area Affected and Cleanup Action Taken.* 25 BBL spill of produced water was released on a 12 x 50 area on the lease road leading to the Ore Ida 14 Fed 10 SWD 0 BBL recovered. An environmental group will be contacted for remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>11/4/15</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>Jeanette.barron@dm.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <u>11/3/15</u> Phone: <u>575.748.1813</u>	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>12/4/15</u>	

\* Attach Additional Sheets If Necessary

2RD.3374