

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1530835676 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 360731	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: BEU Hackberry 34 Federal #001	Facility Type: Tank Battery/SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40288
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	19S	31E	800	North	825	East	Eddy

Latitude 32.622136° Longitude -103.850901°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 927 bbls	Volume Recovered 390 bbls
Source of Release Charge pump connection	Date and Hour of Occurrence 10/25/2015 time unknown	Date and Hour of Discovery 10/25/2015 12 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)	
By Whom? Brad Blevins	Date and Hour 10/25/2015 7 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A connection on the charge pump by-pass line failed. The connection was repaired.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 27,045 square feet of caliche pad within the fenced battery area. Vacuum trucks recovered standing fluids. The impacted area was scraped and 132 cubic yards of saturated caliche surface soils were removed to a NMOCD approved disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman	Approval Date: 11/4/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/03/2015 Phone: 432-661-0571	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 12/4/15

2RP-3376

NM OIL CONSERVATION
ARTESIA DISTRICT
NOV 03 2015
RECEIVED