

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1531455437

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <u>0137</u>	Contact Mike McMahan Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.706.4165
Facility Name State BW Com 1	Facility Type Gas

Surface Owner State	Mineral Owner State	API No. 30-015-23996
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 27	Township 18S	Range 28E	Feet from the 1980	North/South Line FNL	Feet from the 660	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.720956

Longitude: -104.157078

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 165 BBL	Volume Recovered 48 BBL
Source of Release Hole in tank	Date and Hour of Occurrence 11/03/15 at 4:35 pm	Date and Hour of Discovery 11/03/15 at 4:35 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Mike Bratcher OCD	
By Whom? Mike McMahan	Date and Hour 11/03/15 5:00 pm	NM OIL CONSERVATION ARTESIA DISTRICT NOV 06 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

A hole in the water tank caused a leak in the dirt dike containment. This tank was already isolated so production was being routed to another tank. A vacuum truck was called out for recovery.

Describe Area Affected and Cleanup Action Taken.*

A 165 BBL oil spill accorded on a 4 X 30 area in a dirt dike containment 48 BBL was recovered. An environmental company will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron

Printed Name: Jeanette Barron

Title: Field Admin Support

E-mail Address: Jeanette.barron@dvn.com

Date: 11-6-15

Phone: 575.748.1813

Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Approved by Environmental Specialist: [Signature]

Approval Date: 11/10/15

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines ☐

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/12/15

2RP-3379