

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**NAB1531626415** **OPERATOR** ☒ Initial Report ☐ Final Report



Name of Company: COG Operating LLC <b>229137</b>	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: ILLUSTRATED MAN FEE COM #001H	Facility Type: Battery	
Surface Owner: Fee	Mineral Owner:	API No. 30-015-41025

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	12	25S	28E	170'	North	900'	West	Eddy

Latitude 32.1515999 Longitude -104.0465775

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 40 bbls Oil	Volume Recovered: 35 bbls Oil
Source of Release: Hole in tank	Date and Hour of Occurrence: 10/12/2015 10:00 am	Date and Hour of Discovery: 10/12/2015 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Wed 10/14/2015 4:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a hole in the bottom of the production tank. Vacuum trucks were dispatched to recover standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined containment; however impacted areas appeared on the outside of the containment. Therefore, Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 11/10/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: 10/26/2015 Phone: 575-748-6940	LATER THAN: 12/12/15	

\* Attach Additional Sheets If Necessary

22P-3382