<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410				State of New Mexico Energy Minerals and Natural Res				Form C-141 Revised August 8, 2011					
				Oil (	Conse	rvation Div	Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.				rict Office in		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			5	1220 South St. Fran					av	cordanee w	IMI (7.1	J.27 [4]4[2](C.	
Santa Fe, NM 87505 Release Notification and Corrective Action													
nARII	52167	STALL	IVEN		callo			cuor		-1 D	<b></b> 1	Einel Bassant	
Name of Company: BOPCO, L.P. 340731						OPERATOR Initial Report Final Repo							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329							
Facility Nar	me: BEU l		Facility Type: Exploration and Production										
Surface Owner: Federal Mineral						Federal	······	API No. 30-015-41861					
LOCATION OF RELEASE													
				North North	h/South Line Feet from the 1215			West Line	County Eddy				
	54		515	000			1215	East		Eudy			
Latitude 32.622370° Longitude -103.852380°													
NATURE OF RELEASE													
Type of Release Crude Oil and Produced Water						Volume of Release 8 bbl oil Volume Recovered 0 bbls							
Source of Release Wellhead tubing						Date and H	our of Occurrenc						
Was Immediate Notice Given?						11/5/2015 at 2 pm         11/5/2015 at 2 pm           If YES, To Whom?         11/5/2015 at 2 pm							
Yes No X Not Required						N/A							
By Whom? N/A Was a Watercourse Reached?						Date and Hour N/A If YES, Volume Impacting the Watercourse.							
		N/A											
If a Watercourse was Impacted, Describe Fully.* N/A ARTESIA DISTRICT													
N/A			سه، نهي		,								
Describe Cause of Problem and Remedial Action Taken.*													
Fluid escaped out of open tubing during work on wellhead by pulling unit. Safety valve was closed. RECEIVED													
Describe Area	Affected a	nd Cleanup A	ction Tak	en *						KEU	EIVE	<u> </u>	
Describe Area Affected and Cleanup Action Taken.* The leak misted 9,820 ft <sup>2</sup> of caliche pad.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or/local lawsanti/or regulations/													
Signature: Num Hulb						OIL CONSERVATION DIVISION							
						16//2							
Printed Name: Amy Ruth						Approved by E	Invironmental Sp	ecialist:	Ma	100	_		
Title: Assi	atant Remed	liation Forem	an			Approval Date	1110115	) е	xpiration D	ate: NH	$F_{-}$		
E-mail Addres	s: AC	Conditions of A	Approval:			Attank - 1	<b>—</b>						
P-4 11/0/2015 P 422 //1 0521						Remediation per O.C.D. Rules & Guidelines							
Date:         11/9/2015         Phone:         432-661-0571         SUBMIT REMEDIATION PROPOSAL NO           Attach Additional Sheets If Necessary         ATED THAN         21/21/2010         0000										<u> </u>			
			4			ATER THA	N: 1414	415		2	Kh-	3383	

.