

Form 3160-5
(March 2012)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*5. Lease Serial No. **NMLC-078775B**

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
Apache Corporation3a. Address
303 Veterans Airport Ln #3000
Midland, TX 797053b. Phone No. (include area code)
432-818-1187

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No. **BARNSDALL FEDERAL #2**9. API Well No. **30-015-42364**10. Field and Pool or Exploratory Area
EMPIRE

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

715' FUL - 90' FEL ULA, SEC 27 T17S R29E11. County or Parish, State
Eddy, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|---|--|---|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input checked="" type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other _____ |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Interim reclamation has been completed. Please see attachments.

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 16 2015

RECEIVED

Accepted for Record Purposes.
Approval Subject to Onsite Inspection.
If BLM Objectives are not achieved,
additional work may be required.
Date: **11-12-15**

Signature: *James A. [Signature]*

Accepted for record
NMOC

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Bruce Baker

Title Environmental Technician

Signature

Bruce Baker

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

APACHE CORPORATION INTERIM RECLAMATION

BARNSDALL FEDERAL #20; S.27,T17S,R29E; 715' FNL & 900' FEL; 30-015-42364;
NMLC-028775B



OVERVIEW OF WELL PAD OF WELL PAD



WEST EDGE OF WELL PAD. POLY LINE RUNS ACROSS CENTER SO CREW PUSHED SOIL UP TO RESEMBLE LANDSCAPE OVER TIME AND ALSO CONCEAL LINE. BERMED AND SEEDDED.

APACHE CORPORATION INTERIM RECLAMATION



SOUTH EDGE OF WELL PAD. THIS AREA IS RECLAIMED TO MATCH EXTERIOR LANDSCAPE. THIS AREA HAS BEEN SEEDED.



THIS IS ON THE SOUTH SIDE (PASTURE SIDE) SHOWING BERM TO PROTECT IR.

APACHE CORPORATION INTERIM RECLAMATION



EAST EDGE OF WELL PAD. THIS IS ALONG THE ROAD, BUT RECLAIMED ANYWAY SINCE IT IS NOT NEEDED. BERMED AND SEEDED.

REMAINING SURFACE FOR DAILY OPERATIONS IS 225' X 170' (0.88ac) .

OTHER INFORMATION: WELL PAD CLEAN OF TRASH AND CONTAMINANTS, PUMP JACK SHALE GREEN