

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DEC 08 2015  
Form C-141  
Revised August 8, 2011

Submitted to the appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

**Name of Company:** BOPCO, L.P. **260737** **Contact:** Bradley Blevins

**Address:** 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 **Telephone No.** 575-887-7329

**Facility Name:** PLU CVX JV BS 017H **Facility Type:** Exploration and Production

**Surface Owner:** Federal **Mineral Owner:** **API No.** 3001540447

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E	150		1980		Eddy

**Latitude:** 32.151179 **Longitude:** 103.81947

### NATURE OF RELEASE

Type of Release: Produced Water/ Crude Oil	Volume of Release: 35 barrels PW. 8 barrels oil	Volume Recovered: 25 barrels PW and 5 barrels oil
Source of Release: 45 elbow/ threads washed out	Date and Hour of Occurrence: 12-5-15 @ 7:30am	Date and Hour of Discovery: 12-5-15 @ 8:10am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson Jim Amos- BLM	
By Whom? Bradley Blevins via Email	Date and Hour: 12-5-15 @ 11:55am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

BOPCO EHS was notified of a release that occurred at the PLU CVX JV BS 017H due to a 45 elbow that washed out in the threads of elbow and nipple. A vacuum truck was called to the location and was able to recover 25 barrels of produced water and 5 barrels of oil.

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was called to the location and was able to recover 25 barrels of produced water and 5 barrels of oil. Once the fluid was recovered by vacuum truck a backhoe was utilized to scrape the heavy saturated material from the well pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman	Approval Date: <u>12/11/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: <u>12-8-15</u> Phone: 432-214-3704	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

**LATER THAN:** 11/6/16

2RP-3440