

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535735405		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Name of Company	Apache Corp 8713	Contact	Craig Maxwell
Address	2350 W. Garland Hobbs N.Mex	Telephone No.	575-441-2568
Facility Name	Hummingbird	Facility Type	
Surface Owner	Federal	Mineral Owner	API No. 30-015-42631

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	1	17 <sup>S</sup>	31 <sup>E</sup>	1650	South	1300	West	Soldy

Latitude <sup>N</sup>32.860854 Longitude <sup>W</sup>103.826986

NATURE OF RELEASE

Type of Release	Oil, water + Gas	Volume of Release	3 BBLs	Volume Recovered	0
Source of Release	Tank Battery Fire	Date and Hour of Occurrence	12-22-15	Date and Hour of Discovery	12-22-15
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade	NM OIL CONSERVATION	
By Whom?	Craig Maxwell	Date and Hour	8:30 AM	ARTESIA DISTRICT	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		DEC 22 2015	

If a Watercourse was Impacted, Describe Fully.\*

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\* At 3:30 AM MST on 12-22-2015 Juan Francisco with Top map Rental Called Loco Hills fire Department and Reported Apache's Hummingbird Battery was on fire. Fire department arrived around 4:30 AM and shut-in wells and contained the fire.

Describe Area Affected and Cleanup Action Taken.\* When gasket blew out on the fire tube an area on the north east side of containment was sprayed. All other fluid was contained inside of the Containment. Vacuum Trucks were called out to pick up any fluid that was left inside of the Containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Craig Maxwell		OIL CONSERVATION DIVISION	
Printed Name: CRAIG MAXWELL		Approved by Environmental Specialist: [Signature]	
Title: Production Foreman		Approval Date: 12/23/15	Expiration Date: N/A
E-mail Address: Craig.Maxwell@apachecorp.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>		
Date: 12-22-15	Phone: 575-441-2568	SUBMIT REMEDIATION PROPOSAL NO 1/24/16	

\* Attach Additional Sheets If Necessary

LATER THAN: 1/24/16

2RP-3462