

# NM OIL CONSERVATION

ARTESTA DISTRICT

DEC 30 2015

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

**RECEIVED**  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB1536455073

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Winston SWD #004	Facility Type	Intake line
Surface Owner	BLM	Mineral Owner	API No. 30-15-30337

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	31	21S	24E					Eddy County, NM

Latitude N 32.43829° Longitude W 104.54519°

## NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	11 bbls	Volume Recovered	0 bbls
Source of Release	Corrosion of an intake pipe in the pump building	Date and Hour of Occurrence	12/04/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis@BBC International	Date and Hour	12/11/2015 @ 11:57 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Corrosion of an intake pipe in the pump building caused 11 bbls of produced water to leak onto the ground. No fluids were recovered and the pipe was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 62' x 50' inside the pump building. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:		Approved by Environmental Specialist:	
Printed Name:	Casey Summers	Approval Date:	12/30/15
Title:	NM Environmental Advisor	Expiration Date:	NA
E-mail Address:	Casey.Summers@oxy.com	Conditions of Approval:	
Date:	12-28-15	Phone:	(575) 513-8289

Attached ☐

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 1/31/16

2RP-3469

\* Attach Additional Sheets IF Necessary