

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM, 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 30 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB153648194 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Cimarrex Energy <i>1102683</i>	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Montana 1 Fee 3	Facility Type production

Surface Owner	Mineral Owner	API No. 30-015-39616
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	01	19S	25E	990	S	330	W	Eddy

Latitude 32.6854 Longitude -104.4459

NATURE OF RELEASE

Type of Release oil/ due to fire	Volume of Release 270 bbls	Volume Recovered 80
Source of Release tank	Date and Hour of Occurrence 12/29/2015	Date and Hour of Discovery 12/29/2015 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson	
By Whom? Christine Alderman	Date and Hour 12/30/2015 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This well is shut in but the center oil tank blew up and out of the containment. When it did it tore the connecting valve off the oil tank next to it. Some fluids got out of the containment and into the pasture area. A vacuum truck was on location after the fire was put out and recovered what fluid it could.

Describe Area Affected and Cleanup Action Taken.*

Tank battery area and some pasture area. An environmental consulting company will assess the impact and develop a workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Supervisor	Approval Date: 12/30/15	Expiration Date: N/A
E-mail Address: calderman@cimarrex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 12/30/2015 Phone: 432-853-7059	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *1/31/16*

2RP3468