

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 08 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1601155099



OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd. 166946	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Sarah State Com #1 O Battery	Facility Type	Gathering
Surface Owner	State	Mineral Owner	API No. 30-015-34693

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	10	19S	29E					Eddy

Latitude N 32.66947° Longitude W 104.06097°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	70 bbls	Volume Recovered	0 bbls
Source of Release	Load line struck by backhoe	Date and Hour of Occurrence	12/31/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD		
By Whom?	Cliff Brunson @ BBC International Inc.	Date and Hour	01/04/2016 in the afternoon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A backhoe struck a load line while clearing snow causing 70 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired/replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 35' x 30' on location inside the berm. Remediation will be completed in accordance with an approved remediation plan from NMOCD.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Casey Summers		Approved by Environmental Specialist 			
Title: NM Environmental Advisor		Approval Date: 1/11/16		Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>			
Date: 1-7-16 Phone: (575) 513-8289		SUBMIT REMEDIATION PROPOSAL NO			

* Attach Additional Sheets If Necessary

LATER THAN: 2/12/16

2RP-3485