

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 11 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action



NAB1601230258		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill			
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077			
Facility Name: COLT STATE SWD #004		Facility Type: SWD			
Surface Owner: State		Mineral Owner:		API No. 30-015-41401	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	5	25D	28E	1066'	North	850	West	Eddy

Latitude 32.1636543 Longitude -104.1154556

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 66 bbls Oil 250 bbls PW	Volume Recovered: 66 bbls Oil 250 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 12/28/2015 12:00 pm	Date and Hour of Discovery: 12/28/2015 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Tue 12/29/2015 3:31 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused when a high volume alarm malfunctioned, due to power failure from storm, resulting in the tank overflowing. Vacuum trucks were dispatched to recover the standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. All fluid was able to be recovered, the facility cleaned, repaired, and put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 1/12/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: January 11, 2016	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

222-3489