

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1601925922

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Roo 22 State #5 Satellite	Facility Type	Satellite

Surface Owner	State	Mineral Owner	API No. 30-015-39497
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	22	17S	28E					Eddy County, NM

Latitude N 32.82176° Longitude W 104.16964°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	20 bbls	Volume Recovered	15 bbls
Source of Release	Vibration of water transfer pump valve caused the ball to come out	Date and Hour of Occurrence	01/08/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	01/08/2016 @ 8:21 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Vibration of a water transfer pump caused the ball to come out of the valve and spill 20 bbls of oil onto the ground. A vacuum truck recovered 15 bbls of oil and the valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 135' x 105' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:		
Printed Name: Casey Summers	Approval Date: <u>1/15/16</u> Expiration Date: <u>N/A</u>		
Title: NM Environmental Advisor	Conditions of Approval: <u>Remediation per O.C.D. Rules & Guidelines</u>		
E-mail Address: Casey.Summers@oxy.com	Attached <input type="checkbox"/>		
Date: <u>1-14-16</u> Phone: (575) 513-8289	SUBMIT REMEDIATION PROPOSAL NO <u>22P-3498</u>		

LATER THAN: 1/15/16

* Attach Additional Sheets If Necessary