

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 26 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602733517

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Cimarex Energy	Contact: Gloria Garza
Address: 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-234-3204
Facility Name: Bonnie 35 Federal Com	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner	API No.: 30-015-42956
------------------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter P	Section 35	Township 25S	Range 26E	Feet from the 200	North/South Line FSL	Feet from the 970	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.0795801765834 Longitude: -104.258295270376

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 BBLS	Volume Recovered: 5 BBLS
Source of Release: Water transfer line	Date and Hour of Occurrence: 1/25/2015	Date and Hour of Discovery: 1/25/2016 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Jeff Robertson	
By Whom? Gloria Garza	Date and Hour: 1/26/2015 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A hammer union on the water transfer line came loose due to vibration from pressure.

Describe Area Affected and Cleanup Action Taken.*
Diversified Environmental Services will remediate the impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gloria Garza	OIL CONSERVATION DIVISION	
Printed Name: Gloria Garza	Signed By: [Signature] Approved by Environmental Specialist:	
Title: ESH Tech	Approval Date: 1/27/16	Expiration Date: N/A
E-mail Address: ggarza@cimarex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 1/26/16	Phone: 432-234-3204	

* Attach Additional Sheets If Necessary

LATER THAN: 1/27/16

2RP-3519