

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JAN 28 2016 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602952102

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	260737	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: JRU #012H		Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22162
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude 32.380851° Longitude -103.883785°

NATURE OF RELEASE



Type of Release	Produced Water	Volume of Release	22 bbls pw	Volume Recovered	5 bbls pw
Source of Release	Discharge flow line	Date and Hour of Occurrence	1/18/2016 time unknown	Date and Hour of Discovery	1/18/2016 4:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD)		
By Whom?	Amy Ruth	Date and Hour	1/19/2016 at 8:21 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The discharge line from the triplex pump to the well head developed a leak below ground surface. Line was isolated, then excavated and repaired.

Describe Area Affected and Cleanup Action Taken.*
The leak affected 7,135 ft² of well pad. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Signed By:  Approved by Environmental Specialist	
Title: EHS Remediation Specialist	Approval Date: 1/29/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1/27/2016 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO <u>31116</u>	

* Attach Additional Sheets If Necessary

LATER THAN:

2R2-3524