NM OIL CONS. ... VATION ARTESIA DISTRICT

Form 3160-4 (August 2007

TERIOR

OCD Artesia

FORM APPROVED . OMB No. 1004-0137

| ļ. | UNITED STATES |
|----|----------------------|
| 7) | DEPARTMENT OF THE IN |
| | DIDEALI OF LAND MANA |

| BUREAU OF LAND MANAGEMENT RECEIVED | | | | | | | | | | | Ext | ores: Jul | ly 31, 2010 | |
|--|--|-------------------------------------|--------------------|----------------------|-------------------|---------------|-------------------------|-----------------------------------|----------------|-------------------------|---|-------------------|--|--|
| | | | | | | | | | | 5: | 5: Lease Serial No. NMLC029395A | | | |
| 1a. Type o | of Well 5 | Oil Wel | | | □ Dry | Other | | | | | | | or Tribe Name | |
| b. Type o | of Completio | n 🔀 I Oth | New Well er | □ W∘ | rk Over | ☐ Deepe | n □Plu - | ig Back | Diff. F | Resvr. | Unit or CA | Agreen | nent Name and No. | |
| 2. Name o | f Operator HE CORPO | BATION | | F-Mait: F | | | Y FOLLIS | P COM | | | Lease Name | | | |
| 3. Address | | ERANS A | AIRPARK L | | | 1 | | lo. (include a | rea code | | API Well No | | 30-015-41989 | |
| 4. Location of Well (Report location clearly and in accordance with Federal requirements)* | | | | | | | | | | 10. | 10. Field and Pool, or Exploratory CEDAR LAKE;GLORIETA-YESA | | | |
| Sec 18 T17S R31E Mer At surface NWSW 1650FSL 800FWL | | | | | | | | | | | | | Block and Survey | |
| At top prod interval reported below Sec 18 T17S R31E Mer | | | | | | | | | | | or Area Se | ec 18 T | 17S R31E Mer 13. State | |
| At total depth NWSW 1650FSL 990FWL | | | | | | | | | | | EDDY COL | UNTY | NM | |
| 14. Date S 04/18/2 | pudded 2014 | | | ate T.D. 4/29/201 | Reached 4 | | D& | e Completed : A 🔼 R !9/2014 | eady to P | rod. | Elevations 37 | (DF, KI '60 GL | B, RT, GL)* | |
| 18. Total I | Depth: | MD TVD | 6416 | | 19. Plug B | ack T.D.: | MD TVD | 6370 |) | 20. Depth B | idge Plug S | | MD TVD | |
| 21. Type E SBGR- | lectric & Otl | her Mecha | nical Logs R | lun (Subi | mit copy of | ach) | | 2 | | vell cored? OST run? | | | s (Submit analysis) s (Submit analysis) | |
| | | and /P | | | -10 | | | | | tional Survey? | ☐ No | Yes | (Submit analysis) | |
| | nd Liner Rec | - | | s set in w | | om Sta | ge Cementer | No. of S | Sks. & | Slurry Vol. | T | | | |
| Hole Size | Size/C | | Wt. (#/ft.) | (ME | | D) | Depth | Type of (| Cement | (BBL) | Cement | | Amount Pulled | |
| 17.500 11.000 | | 13.375 H-40 48.0 8.625 J-55 32.0 | | + | | 335 3508 | | 610 1380 | | | 0 . | | | |
| 7.875 | | | | 6376 | | | 920 | | | . 0 | | | | |
| | <u> </u> | | | - | | | _ | ļ | | | | | | |
| | | | | | 1 | } | | | | | } | | | |
| 24. Tubing | | | | | | | | | | | • | | | |
| Size 2.875 | Depth Set (N | 4D) P: 6348 | acker Depth | (MD) [| Size | Depth Set | (MD) F | acker Depth | (MD) | Size D | epth Set (M | D) | Packer Depth (MD) | |
| 25. Produci | | | | | ····· | 26. Perf | oration Reco | ord | | | | | | |
| | ormation | VOCK | Тор | Bottom | | | Perforated Interval Siz | | | | No. Holes | DD0[| Perf. Status | |
| A) B) U | PADE JPPER BLIN | | | 4586 5102 | 5050 5758 | | <u>-</u> | 4586 TO 5050 5102 TO 5758 | | | 24 PRODUCING 25 PRODUCING | | | |
| | | | | | 6276 5856 TO 6276 | | | | | | | | DUCING | |
| D) | acture, Treat | ment Can | nent Sauceze | Ftc | | L | | | | | | <u> </u> | | |
| | Depih Interva | | Tient Squeeze | ., 1510. | | a 4 | Ar | nount and Ty | ype of Ma | aterial | | | | |
| | 45 | 86 TO 62 | 76 #10 GEL | 274 BBL | ., #20 GEL 1 | 1,514 BBI | , 16/30 PRC | PPANT #413 | 3,911, AC | ID 321 BBL | | | | |
| | | | | | <u> </u> | | | | | - | | | | |
| | | | | • | | | | | | | | | | |
| | on - Interval Test | A | Test | Oil | Gas | Water | Oil Gra | avity | Gas | Producti | on MalGC | EPT | ED FOR REC | |
| | Date 06/29/2014 | Tested 24 | | BBL 75.0 | MCIF 224.0 | BBL 14 | Corr. / | | Gravity | | 1 1 | | IPING UNIT | |
| hoke | Tbg. Press. | Csg. | 24 Hr. | Oil | Gas | Water | Gas:Oi | | Well Sta | tus | LLLCIN | | | |
| | Flwg. SI | Press. | Rate | BB1, | MCF | BBL. | Ratio | 2987 | PC | ow . | 1 / | -FE | B 3 2015 | |
| 28a. Product | tion - Interva | | | | | | | | | | 16 | ŢŲ. | brak Llan | |
| | Test Date | Hours Tested | Test Production | Oil BBI. | Gas MCF | Water BBL | Oil Gra Corr, A | | Gas Gravity | Producti | ori Methibili R | LAU O CARLS | F LAND MÁNAGEM BAD FIELD OFFICE | |
| | Thg. Press. Flwg. | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | Water BB1, | Gas:Oi Ratio | j · | Well Sta | nus | | | | |
| l. | e1 | | | | | 1 | 1 | | ı | | | | ν | |

(See Instructions and spaces for additional data on reverse side)
ELECTRONIC SUBMISSION #287655 VERIFIED BY THE BLM WELL INFORMATION SYSTEM

Reclamation ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Duc: 12/29/14

| 28b. Produ | ction - Interv | al C | | | | | | | | | | | |
|--|---|--------------------------|---|---|---|---|--|-----------------------------------|--|-------------------|-----------------|--|--|
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oil Gravity Corr. API | G2s Grav | nly | Production Method | | | |
| Choke Size | Thg. Press. Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBI. | Gas MCF | Water BBL | Gas;Oil Ratio | Weil | Status | <u> </u> | | | |
| 28c. Produ | ction - Interv | al D | | | - | | | | | • | | **** | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oit Gravity Corr. API | Gas Grav | ity | Production Method | | | |
| Choke Size | Tog. Press. Flwg. S1 | Csg. Press. | 24 Hr. Rate | Oil BBI. | Gas MCF | Water BBL | . Gas:Oil Ratio | Well | Status | | | | |
| 29. Dispos SOLD | | old, used | l for fuel, vent | ed, etc.) | | | | • | | | | | |
| Show a tests, ir | ıll important z | ones of r | nclude Aquifer porosity and co tested, cushio | ontents there | of: Cored in tool open, | ntervals and | l all drill-stem d shut-in pressures | | 31. For | mation (Log) Ma | arkers | | |
| I | Formation | | Тор | Bottom Descriptions, Contents, etc. | | | | | Name To Mean | | | | |
| ### 286 #### ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 ### 286 # | | | | 518 1341 1484 1762 2373 3110 4582 4651 | 341 SALT 484 SALT 762 SANDSTONE 373 SANDSTONE/CARBONATE 110 SANDSTONE/CARBONATE 582 CARBONATE | | | | RUSTLER TANSIL SALT BOTTOM SALT YATES SEVEN RIVERS QUEEN SAN ANDRES GLORIETA | | | Meas. Depth 286 518 1341 1484 1762 2373 3110 4582 | |
| 22 (7) | | | | | | | | · | | | | | |
| 1. Elect 5. Sund | ry Notice for | cal Logs | (I full set req | erification | 6. | 2. Geologic Report 3 6. Core Analysis 7 | | | | ort | 4. Directions | | |
| • | certify that th | | Electro Comr | nic Submiss For Al | ion #28765 PACHE CO | 55 Verified ORPORAT | rect as determined by the BLM Wel TION, sent to the by DEBORAH HA | l Inform: Carlsbac AM on 02 | ation Syst | em. () | hed instruction | s): | |
| Signatur | Signature (Electronic Submission) Date 01/12/2015 | | | | | | | | | | | | |
| Title 18 U.S of the United | .C. Section 10 d States any fa | 001 and T alse, ficti | Fitle 43 U.S.C. tious or fradul | Section 121 ent statemen | 2, make it a ts or represe | crime for entations as | any person knowing to any matter with | igly and v | willfully to isdiction. | make to any dep | partment or ag | ency | |