

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 15 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1107837012
Name of Company: BOPCO, L.P. 240737
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220
Facility Name: Golden 8 Federal #001
Operator: Amy Ruth
Contact: Amy Ruth
Telephone No. 575-887-7329
Facility Type: Exploration and Production
Surface Owner: Federal
Mineral Owner: Federal
API No. 30-015-26931

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	8	21S	29E	1650	South	2180	West	Eddy

Latitude 32.491242° Longitude -104.008322°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	30 bbls	Volume Recovered	7 bbls
Source of Release	Heater Gasket	Date and Hour of Occurrence	2/1/2016 time unknown	Date and Hour of Discovery	2/1/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)		
By Whom?	Brad Blevins	Date and Hour	2/2/2016 3:26 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Gasket seal in heater treater ruptured and released fluids onto location and pasture. Operator switched out vessels until repairs could be made to treater gasket.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 3060 square feet of well pad and approximately 600 square feet of pasture to the east of the battery. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: EHS Remediation Specialist	Approval Date: 3/21/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	
Date: 3-15-2016 Phone: 432-661-0571	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/21/16	

* Attach Additional Sheets If Necessary

2RP-3612