

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

MAR 15 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1608139873 **210731** **OPERATOR** ☒ Initial Report ☐ Final Report



Name of Company: BOPCO, L.P.	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #036	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27686

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	I	23S	30E	1980	North	1860	East	Eddy

Latitude 32.335850° Longitude -103.861675°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	17 bbls	Volume Recovered	5 bbls
Source of Release	Valve on Circulating Pump	Date and Hour of Occurrence	2/1/2016 Time Unknown	Date and Hour of Discovery	2/1/2016 8:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* A discharge bleed valve was left open on the circulating pump. The valve was closed and the handle was removed from the valve.					
Describe Area Affected and Cleanup Action Taken.* The leak affected 1575 square feet of well pad within the process equipment area. Standing fluids were recovered.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Amy C. Ruth		Approved by Environmental Specialist: 			
Title: EHS Remediation Specialist		Approval Date: 3/21/16		Expiration Date: N/A	
E-mail Address: ACRuth@basspet.com		Conditions of Approval: <input type="checkbox"/> Attached			
Date: 3/15/2016 Phone: 432-661-0571		Remediation per O.C.D. Rules & Guidelines			

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/21/16

2RD-3617