

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised July 18, 2013

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

MAR 02 2016

OIL CONSERVATION DIVISION
RECEIVED
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-00802
5. Indicate Type of Lease STATE [] FEE [x]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name WEST RED LAKE UNIT
8. Well Number #1
9. OGRID Number 277558
10. Pool name or Wildcat Red Lake, Queen-Grayburg-San Andres (51300)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3374' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [x] Gas Well [] Other []
2. Name of Operator LIME ROCK RESOURCES II-A, L.P.
3. Address of Operator c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401
4. Well Location Unit Letter M : 810 feet from the South line and 960 feet from the West line
Section 6 Township 18-S Range 27-E NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3374' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM [x]
OTHER: Repair Casing [x]

SUBSEQUENT REPORT OF:

- REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/29/16: Discovered 5-1/2" csg collapsed at surface. MIRUSU. TOH w/rods, pump, & tbg. Set RBP @ 975'. W/pkr @ 3'. PT 5-1/2" csg to 300 psi-OK. Released rig.

LIME ROCK RESOURCES II-A, L.P. plans to repair the collapsed csg by digging out around the part, cutting off the bad csg & welding on new csg. The csg will then be pressure tested & the production equipment rerun & the well returned to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Pippin TITLE Petroleum Engineer - Agent DATE 3/1/16

Type or print name Mike Pippin E-mail address: mike@pippinllc.com PHONE: 505-327-4573

For State Use Only APPROVED BY: [Signature] TITLE: [Signature] DATE: 3/1/16
Conditions of Approval (if any):

NM OIL CONSERVATION
ARTESIA DISTRICT
MAR 02 2016
RECEIVED