

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 30 2016

Form C-141
Revised August 8, 2011

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit report to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1609150946

OPERATOR

X Initial Report ☐ Final Report

Name of Company Lime Rock Resources II-A, L.P. 277558	Contact Mike Barrett
Address R347-2 North 26 Street, Artesia, New Mexico 88210	Telephone No. 505-353-2644
Facility Name Atoka San Andres Unit No. 141	

Surface Owner Fee	Mineral Owner State	API No. 30-015-10550
-------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 13	Township 18S	Range 26E	Feet from the 2310'	North/South Line FSL	Feet from the 2310'	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	----------------

Latitude 32.74685 Longitude 104.33441

NATURE OF RELEASE

Type of Release Produced waters	Volume of Release 15 bbls	Volume Recovered 10 bbls
Source of Release injection line	Date and Hour of Occurrence 3/26/2016 10:30am	Date and Hour of Discovery 3/26/2016 10:30am
Was Immediate Notice Given? Yes No X Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A line located near the wellhead at WIW well developed a pinhole size leak, the line was immediately shut-in, and the line was repaired. A vacuum truck was immediately brought to the facility, standing fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is located on location and in farm land south of the WIW well. This area was measured to be 10'-30' W x 175' L. R.T. Hicks Consultants has been contracted for the corrective actions on release. **Work Plan:** The impacted material from the release will be excavated and transported to and NMOCD approved Land Fill for disposal. Conformation soil samples will be collected upon completion of excavation. Like material will be utilized to backfill the excavated area.

Site Ranking: Depth to ground water <50', Wellhead protection Area >1000', Distance to Surface Water Body >1000'. Total Ranking score: 20.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

AMENDED

Signature: 

Printed Name: Michael Barrett

Title: Production Superintendent

E-mail Address: Michael Barrett <mbarrett@limerockresources.com>

Date: 3/30/2016

Phone: 505-353-2644

OIL CONSERVATION DIVISION

Approved by Environmental Specialist

Approval Date: 3/31/16

Expiration Date: NA

Conditions of Approval:

Attached ☐

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 5/11/2016

2RP-3627

* Attach Additional Sheets If Necessary