

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 06 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1609935974		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Oxy Permian Ltd. 192463		Contact Casey Summers			
Address 6 Desta Drive, Midland, TX 79705		Telephone No. (575) 513-8289			
Facility Name Smokey Bits State Com #2H		Facility Type Well location			
Surface Owner State		Mineral Owner		API No. 30-015-40196	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	18S	30E					Eddy

Latitude N 32.71024° Longitude W 103.93373°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 150 bbls	Volume Recovered 0 bbls
Source of Release 3rd Party Frac tank spill	Date and Hour of Occurrence 12/02/2015	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 12/03/2015 @ 2:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A 3rd party contractor spilled 150 bbls of produced water from Frac Tank. No fluids were recovered and the issue was resolved.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 600' x 5' off location near the Smokey Bits #6H. Remediation will be completed in accordance with an approved remediation plan from NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 4/7/16	Expiration Date: N/A
E-mail Address: Casey.Summers@oxy.com		Conditions of Approval:	
Date: 4-6-16	Phone: (575) 513-8289	Remediation per O.C.D. Rules & Guidelines	
		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: 5/11/16	

* Attach Additional Sheets If Necessary

2RP-3638