

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

State of New Mexico  
Energy Minerals and Natural Resources

APR 13 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

## Release Notification and Corrective Action

2RP-3457

NAB/535131870

### OPERATOR

Initial Report ☒ Final Report

Name of Company Finney Oil Company	Contact Darrell Finney
Address P.O. Box 1569, Artesia, N.M. 88210	Telephone No. 575-365-5639
Facility Name Southland State No.2	

Surface Owner State	Mineral Owner State	API No. 30-015-25212
---------------------	---------------------	----------------------

### LOCATION OF RELEASE

Unit Letter B	Section 7	Township 19S	Range 28E	Feet from the 330'	North/South Line North	Feet from the 2310'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.32.68113 Longitude 104.21329

### NATURE OF RELEASE

Type of Release Oil	Volume of Release 20 bbl.	Volume Recovered 0
Source of Release tank battery	Date and Hour of Occurrence	Date and Hour of Discovery 12/15/2015 12:30 pm
Was Immediate Notice n? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade	
By Whom? Darrell Finney	Date and Hour 12/15/2015 12:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

High wind damaged the water leg attached to the gun barrel causing a release of 20 bbl. oil, the impacted area was the bermed area of the tank battery, the impacted area located outside of the bermed area was measured to be 3'-21' wide x 105' Long.

Describe Area Affected and Cleanup Action Taken.\*

The impacted material from the release was excavated and transported to Lea Land LLC. For disposal. Confirmation soil samples were collected, analytical results were received from Cardinal Laboratories, Inc. The excavated area was backfilled to grade and new berms were constructed at the tank battery.

See attached Remediation plan/Final Closure report dated April 11, 2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Darrell Finney</i>	OIL CONSERVATION DIVISION	
Printed Name: Darrell Finney	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Finney Oil Company	Approval Date: 4/13/16	Expiration Date: NA
E-mail Address: darrellfinney@yahoo.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 4/11/2016	Phone: 575-365-5639	

\* Attach Additional Sheets If Necessary

2RP-3457