

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

APR 13 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☒ Final Report

**Name of Company** Oxy Permian Ltd. **Contact** Casey Summers

**Address** 6 Desta Drive, Midland, TX 79705 **Telephone No.** (575) 513-8289

**Facility Name** Cypress 33 Federal #1H Water Tank **Facility Type** Battery

**Surface Owner** BLM **Mineral Owner** **API No.** 30-015-36321

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	23S	29E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

<b>Type of Release</b> No release, lightning strike	<b>Volume of Release</b> 0 bbls	<b>Volume Recovered</b> 0 bbls
<b>Source of Release</b> A lightning strike caused fire damage to the water tank, but no fluids were released	<b>Date and Hour of Occurrence</b> 04/10/2016	<b>Date and Hour of Discovery</b>
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Mike Bratcher- NMOCD	
<b>By Whom?</b> Cliff Brunson @ BBC International Inc.	<b>Date and Hour</b> 04/11/2016	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b>	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A lightning strike caused fire damage to a water tank but no fluids were released. Initial action was taken to ensure the fire had been extinguished.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is the water tank on location. Remediation was completed by ensuring the fire was extinguished and no fluids were released.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Casey Summers	Approved by Environmental Specialist <i>[Signature]</i>	
<b>Title:</b> NM Environmental Advisor	<b>Approval Date:</b> 4/14/16	<b>Expiration Date:</b> N/A
<b>E-mail Address:</b> casey_summers@oxy.com	<b>Conditions of Approval:</b> FINAL	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 4-13-16 <b>Phone:</b> (575) 513-8289		

\* Attach Additional Sheets If Necessary

2RP-3645