NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico **Energy Minerals and Natural Resources**

APR 1 4 2016

Form C-141 Revised August 8, 2011

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III

1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in RECEIVEINCE with 19.15.29 NMAC.

0000	nini.ai	Fail	Kele				orrective A	ction		1D :		n: 12
NAB 1010 626594 6137					<u> </u>	OPERA'		al Report		Final Repo		
Name of Company Devon Energy Production Company Address 6488 Seven Rivers Hwy Artesia, NM 88210						Contact Brett Fulks, EHS Professional Telephone No. 432,301,3223						
Facility Name Grandi 22-3						Facility Type Gas						
Surface Ov				Mineral		API No 30-015-33922						
SULINCE ON	упет											
						OF RE						
Unit Letter Section Township Range Feet from the Nor. A 22 22S 27E 660						South Line FNL	Feet from the 1210	East/West Line County Eddy				
	<u> </u>	`	<u> </u>	Latitud	e:	L	ongitude:					
				NAT	TURE	OF REL		<u>.</u>				
Type of Rele Produced Wa	iter				Volume of Release Unknown Volume Recovered: 0							
Source of Release Produced water line to SWD was damaged by third party 12 15 15						Date and Hour of Occurrence Date and Hour of Discovery 3/18/2016 12:00PM 3/18/2016 12:00PM						
Was Immedi		Given?		No □ Not R	, ,	If YES, To			3/10/2010	12.001 141		
By Whom?					Date and Hour							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse						
			Yes 🛚	No No								<u>.</u>
If a Waterco	urse was li	mpacted, Des	cribe Ful	ly.*								
system at some the home own 3/18/16 to ide	ne point. In ner contacto entify if and ne was iden	December of and Devon Ener lexactly when attified right un	2015, Dev rgy, believ the leak	von Energy produ ving that the line l was. Then on 3/2	iced throi had devel 21/16, De	ugh the line t loped a leak won excavate	iled to contact Do to a commercial S due to staining in ed a small area are d over the top of	WD for his yard ound the	a short dur d. Devon Er e line to ide	ration of tim nergy pressu ntify how th	ie. In M ired the ie line l	larch of 2016 line on had failed. A
The area affe	ected is a pr		ial yard at	Taken.* the approximate adiate the spill.	coordina	te of: Lat:32	.383947 Lon:104.	.168534	in WGS84	. An enviro	nmental	l remediation
regulations al public health should their o	l operators or the envir operations h iment. In a	are required to ronment. The ave failed to a ddition, NMC	o report ar acceptance adequately OCD accep	nd/or file certain in ce of a C-141 reprint investigate and i	release no ort by the remediate	otifications a NMOCD m contaminati	knowledge and und perform correct parked as "Final Right to that pose a thrue the operator of	ctive act teport" o reat to g	tions for rel does not rel round wate	eases which ieve the ope r, surface wa	may en trator of ater, hu	ndanger f liability man health
Signature: 7	1.4	E M.		OIL CONSERVATION DIVISION								
			<u> </u>		Signed By Mily Drundese_							
Printed Name	: Brett Ful	iks		Approved by Environmental Specialist:								
Title: EHS Professional						Approval Date: 4 15 16 Expiration Date: NA						
E-mail Address: brett.fulks@dvn.com					•	Conditions of Approval: Attached			ı 🗆			
Date: 04/07			e: 432-30	1-3223	Re	mediatio	n per O.C.D.	Rules	& Guide	lines		
Attach Addi	tional Shee	ets If Necess	ary				MEDIATION	PROP	OSAL N	0	2R1	7-3647

LATER THAN: __5//5/