

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company : LIME ROCK RESOURCES A, L.P.	Contact : Jerry Smith	
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-748-9724	
Facility Name : AID 24 State Produced Water Transfer Line	Facility Type: Produced Water Transfer Line	
Surface Owner : State	Mineral Owner	Lease No. : API #30-015-22878

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	17S	28E	900	FSL	990	FWL	Eddy

Latitude 32.80140 Longitude -104.152254

NATURE OF RELEASE



Type of Release : Produce Water	Volume of Release : 40 bbls	Volume Recovered: 10
Source of Release : Poly Line	Date and Hour of Occurrence: 7/21/11 10:00 am	Date and Hour of Discovery: 7/21/11 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD/Mike Bratcher by voicemail	
By Whom? Mike Stubblefield	Date and Hour : 7/21/11 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A connection in a new 4" poly line parted causing the release. The line was isolated and a vacuum truck was immediately brought to location. All free standing fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*
Talon/LPE was contracted for the correction of this release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jerry Smith	Approved by District Supervisor: 	
Title: Assistant Production Supervisor	Approval Date: 4/22/16	Expiration Date: N/A
E-mail Address: jsmith@limerockresources.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 1/20/11 Phone: 575-748-9724		

* Attach Additional Sheets If Necessary

2RP-809