District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

APR 2 1 2016 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Santa Fe, NM 87505 **Release Notification and Corrective Action**

State of New Mexico

Energy Minerals and Natural Resources

**Oil Conservation Division** 

1220 South St. Francis Dr.

RATOR X Initial Report Final Report
Leslie Garvis
one No. 817-583-8730
Type Well
t

Sumfrag Outpar DIM	Mineral Owner BLM	API No. 30-015-41177
Surface Owner BLM	I Mineral Owner BLM	API No. 30-015-41177

LOCA	TION	OF	REL	EASE

Unit Letter	Section	Township	Range	Fect from the	North/South Line	Feet from the	East/West Line	County
В	23	175	30E	990	North	1650	East	Eddy

Latitude 32. 8245 0 Longitude 103. 959 40

Type of Release Oil/Water	Volume of Release 18 BO/40 BW	Volume Recovered 10BO/30BW					
Source of Release Cracked Line at Well Head	Date and Hour of Occurrence	Date and Hour of Discovery 4/21/16/11:00am					
Was Immediate Notice Given?	If YES, To Whom?	$\bigcirc$					
Yes 🗌 No 🗍 Not Required	Phone Call to BLM - S. Tucker, OCD - H.P.	atterson (10)					
By Whom? Leslie Garvis	Date and Hour 4/21/16 1530	Cell Z:49pm MM					
Was a Watercourse Reached?	If YES. Volume Impacting the Wat	tercourse.					
🗋 Yes 🔀 No	N/A						
If a Watercourse was Impacted, Describe Fully.*							
N/A							
Describe Cause of Problem and Remedial Action Taken.*		· · · · · · · · · · · · · · · · · · ·					
There was a crack in a 1" line coming off the well head. Line has been repaired	and out back into service.						
There was a stage in a 1- find confing on the wait field. End has been repaired	and put block into doi noo.						
Describe Area Affected and Cleanup Action Taken.*							
The total areas affected were approx. 300'x10'x1' and 150'x5'x1'. Of this total amount, the s	sections that ran off the pad measured approx.	30'x2' and 20'x20'. All standing fluid has been picked up.					
The impacted area will be assessed and remediated per regulatory standards.							
I hereby certify that the information given above is true and complete to t	he best of my knowledge and underst	and that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release t	otifications and perform corrective ac	tions for releases which may endanger					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability							
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health							
or the environment. In addition, NMOCD acceptance of a C-141 report of	loes not relieve the operator of respon	sibility for compliance with any other					
federal, state, or local aws and/or regulations.							
	OIL CONSERY	VATION DIVISION					
Proling Annul		$\neg \neg $					
Signation Signation		4///					
Printed Name: Leslie Garvis	Approved by Environmental Speciali	ist: (Whath					
Printed Name: Leslie Garvis							
Title: Regulatory Coordinator	Approval Date: 4 25 10	Expiration Date: N/A					
E-mail Address; lgarvis@burnettoil.com	Conditions of Approval:						
		Attached					
Date: 4/21/16 Phone: 817-583-8730	Remediation per O.C.D. Rule	es & Guidelines					
* Attach Additional Sheets If Necessary	SUBMIT REMEDIATION, PRO	DPOSAL NO AOD TO K					
· · ·	ATER THAN: 526	<u>115</u> ZKY UDU					

## NATURE OF RELEASE