

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB/6/24/292/101

Name of Company: COG Operating LLC <i>229137</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Contact: Robert McNeill		
Facility Name: YELLOWSTONE 3 FEDERAL #003		Telephone No. 432-230-0077		
		Facility Type: Battery		
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-39823	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	03	26S	25E	1980'	South	660'	West	Eddy

Latitude 32.0699768 Longitude -104.3898697

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 bbls PW	Volume Recovered: 12 bbls PW
Source of Release: Load line	Date and Hour of Occurrence: 4/12/2016 12:00 pm	Date and Hour of Discovery: 4/12/2016 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
APR 28 2016

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the load line. Vacuum trucks were dispatched to recover standing fluid.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

The majority of this release occurred on pad however a streamer ran off location to the southeast for 140'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>5/2/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: April 28, 2016	SUBMIT REMEDIATION PROPOSAL NO. <i>229-3668</i>	
Phone: 432-683-7443	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary.

LATER THAN: *013/16*