

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1613058084 229137 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	LOVING 1 STATE #003	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-32446

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	01	24S	27E	1980	North	660	West	Eddy

Latitude 32.6090431 Longitude 104.452919

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: Oil 1bbl Produced Water 35bbls	Volume Recovered: Oil 1bbl Produced Water 33bbls
Source of Release: Produced Water Tank	Date and Hour of Occurrence: 04-26-2016 10:01pm	Date and Hour of Discovery: 04-26-2016 10:01pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Amber Groves - SLO	
By Whom? Robert Grubbs Jr	Date and Hour: 04-29-2016 12:35pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 06 2016

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a surface casing valve left open to a line that dumped into the water tank causing it to run over. A vacuum truck was dispatched to remove all free standing fluids.

Describe Area Affected and Cleanup Action Taken.*

Initially 1bbl of oil and 35bbls of produced water were released due to a surface casing valve left open to a line that dumped into the water tank causing it to run over. The valve was closed to prevent this from occurring again. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Robert Grubbs Jr.</u>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Senior Environmental Coordinator	Approval Date: <u>5/6/16</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>rgrubbs@concho.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05-06-2016 Phone: 432-683-7443	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary.

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 6/10/16

2RP-3681