

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

11AB1613135740

246289

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	WPX Energy Inc/ RKI E&P, LLC	Contact	Lucas Smith
Address	3500 One Williams Center Tulsa, OK 74172	Telephone No.	539-573-0176
Facility Name:	North Brushy Draw	Facility Type :	Produced water gathering line

Surface Owner: Federal Mineral Owner: Federal API No. 30-015-42220

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	1	26S	29E	330	FSL	500	FWL	Eddy

Latitude: 32.0926101 Longitude: -103.9468205

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 200 Bbls	Volume Recovered: 70 Bbls
Source of Release Leaking connection on header manifold	Date and Hour of Occurrence 05/08/16	Date and Hour of Discovery 05/08/16 - 11:50hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Message left at Artesia Field Office	
By Whom? Lucas Smith	Date and Hour: 05/08/16 - 1504hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted. Describe Fully.* N/A


Describe Cause of Problem and Remedial Action Taken.*

Produced water gathering system header developed a leak. The system was shut in and the free fluids were vacuumed up. The remaining impacted soils will be removed for disposal and confirmation samples will be collected.

Describe Area Affected and Cleanup Action Taken.*

Primarily the fluids pooled on the pipeline right-of-way. At one point the fluid left the right-of-way and followed a low spot approximately 150yds by 4ft.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Lucas Smith	Approved by Environmental Specialist: 	
Title: EHS Manager	Approval Date: 5/10/16	Expiration Date: N/A
E-mail Address: Lucas.smith@wpenergy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO 246289	
Date: 05/09/16 Phone: 539-573-0176	LATER THAN: 6/10/16	

* Attach Additional Sheets If Necessary

ARTESIA DISTRICT

MAY 09 2016

RECEIVED