

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

MAY 17 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
100 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1613453134

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC 229137	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	CONTINENTAL A STATE BATTERY	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-29696
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	17S	29E	330	North	1409	West	Eddy

Latitude 32.8119583

Longitude 104.1168976

NATURE OF RELEASE

Type of Release:	Oil and Produced Water	Volume of Release:	10bbls of oil 6bbls of produced water	Volume Recovered:	10bbls of oil 4bbls of produced water
Source of Release:	Steel flowline	Date and Hour of Occurrence:	05-09-2016 2:45pm	Date and Hour of Discovery:	05-09-2016 2:45pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" steel line corroded due to age. Replaced the corroded section of pipe with a new joint of 3" steel pipe.

Describe Area Affected and Cleanup Action Taken.*

A 20' X 4' area inside the facilities dike and a 1' X 1' outside the dike in the pasture were affected by the release. All free fluids were recovered; an initial cleanup was performed and the facility was put back into service. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Signed By:	<i>[Signature]</i>
Title:	Senior Environmental Coordinator	Approved by Environmental Specialist:	
E-mail Address:	rgrubbs@concho.com	Approval Date:	5/18/16
Date:	05-17-2016	Expiration Date:	N/A
Phone:	432-683-7443	Conditions of Approval:	
Each Additional Sheets If Necessary		Remediation per O.C.D. Rules & Guidelines	<input type="checkbox"/> Attached

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

5/18/16

ARP-3699