

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
MAR 23 2010  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

NAB 1614439801 279579 OPERATOR  Initial Report  Final Report

Name of Company BP America Production Company Contact Steve Pacheco

Address PO Box 129 Artesia, NM 88210 Telephone No. 575-677-3642

Facility Name Riverwolf Unit No. 10 Facility Type Oil Well

Surface Owner BLM Mineral Owner BLM Lease No. API # 3001500639

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>O</u>	<u>35</u>	<u>17S</u>	<u>27E</u>	<u>410</u>		<u>2235</u>		<u>Eddy</u>

Latitude 32.7845001 Longitude -104.248085

**NATURE OF RELEASE**

Type of Release <u>Oil and Produced Water</u>	Volume of Release <u>Unknown</u>	Volume Recovered <u>Unknown</u>
Source of Release <u>Riverwolf Unit # 10 Well Bore</u>	Date and Hour of Occurrence <u>Unknown</u>	Date and Hour of Discovery <u>October 27, 2009</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <u>Well was plugged by BP America Production Company, March 2009. Historical release found when new lessee was preparing to re-enter well, October 2009. Impacted soil will be removed and disposed of at Lea Land Landfill. The site will be backfilled with clean dirt.</u>		
Describe Area Affected and Cleanup Action Taken.* <u>Area impacted is immediately around the Riverwolf Unit #10 well bore.</u>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Steve M. Pacheco</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <u>Steve M. Pacheco</u>	Approved by District Supervisor: <u>[Signature]</u>	
Title: <u>Southeast New Mexico Team Lead</u>	Approval Date: <u>5/20/10</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Steve.Pacheco@bp.com</u>	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: <u>3/4/2010</u> Phone: <u>575-677-3642</u>		

\* Attach Additional Sheets If Necessary

2RP-3707