

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1616041012 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>2100737</u>	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU 146	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31007

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	31	23S	30E	660		810		Eddy

Latitude: 32.55810 Longitude: 103.914818

NATURE OF RELEASE

Type of Release: Crude Oil/ Produced Water	Volume of Release: 4 barrels oil, 4 barrels PW	Volume Recovered: 1.5 barrels oil, 0.5 barrels PW
Source of Release: Stuffing Box	Date and Hour of Occurrence: 5-30-16 @ 5:00pm	Date and Hour of Discovery: 5-30-16 @ 5:15pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT

If a Watercourse was Impacted, Describe Fully.*

JUN 06 2016

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Packing in stuffing box failed. A vacuum truck was called to the location and was able to recover 1.5 barrels of oil and 0.5 barrels of produced water.

Describe Area Affected and Cleanup Action Taken.*

Packing in stuffing box failed and released fluid to the ground surface of well pad and pasture area. A vacuum truck was called to location to recover the standing fluid. A remediation crew will be scheduled to conduct an initial scrape and sampling event.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman		Approval Date: <u>6/8/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <u>6-6-16</u> Phone: 432-214-3704		SUBMIT REMEDIATION PROPOSAL NO <u>714116</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 7/14/16

220-3719