

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 03 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NABILE 039402

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: COG Operating LLC 229137		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-683-7443	
Facility Name: BURCH KEELY UNIT 18A Battery		Facility Type: Battery	
Surface Owner: Federal		Mineral Owner: Federal	
		API No. NA 30-015-36263	

LOCATION OF RELEASE

BKU 411

Unit Letter E	Section 18	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.836628 Longitude -104.0164337

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 30 bbls Oil ; 40 bbls PW	Volume Recovered: 25 bbls Oil ; 35 bbls PW
Source of Release: Separator	Date and Hour of Occurrence: 5/26/2016 unknown	Date and Hour of Discovery: 5/26/2016 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Shelly Tucker - BLM	
By Whom? Amanda T. Davis	Date and Hour: 5/26/2016 6:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a gasket failure on a separator. Vacuum trucks were dispatched to recover all standing fluid and Microblaze was applied to the impacted pasture area. The equipment was also pressure washed.		
Describe Area Affected and Cleanup Action Taken.* The majority of this release was contained within the lined bermed area; however a spray of fluid impacted the pasture area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 6/8/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: June 3, 2016 Phone: 575-748-6940	LATER THAN: 7/9/16	

* Attach Additional Sheets If Necessary

2RP-3717