NM OIL CONSERVATION

District I 1625 N. French Dr., Hobbs, NM 8824RTESIA DISTRICT Energy Minerals and Natural Resources

District II 811 S. First St., Artesia, NM 88210 JUN 1 3 2016 District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 8**R5CFIVED**

Oil Conservation Division 1220 South St. Francis Dr.

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505											
Release Notification and Corrective Action											
hAR	1016 635458	•	OPERATOR			⊠ Initi	al Report		Final Report		
Name of Company Bettis, Boyle & Stovall 2/15					Contact Kyle Berend						, , , , , , , , , , , , , , , , , , ,
	P.O Box 1240, Graha	Telephone No. 940-549-0780									
Facility Na	me Latham Federal		Facility Type Oil & Produced Water Storage Facility								
Surface Ow	/ner	BLM API No. 30-015-24731									
LOCATION OF RELEASE											•
Unit Letter	Section Township	n/South Line Feet from the East/West Line County									
Onn Botter	Section Township	Range	Feet from the			T cet irom the	Lust	West Ellie	County		
P	15 25S	29E	660	So	uth	530	Ea	nst	st Eddy		
٠		Ĺa	titude		Longitud	le					
NATURE OF RELEASE											
Type of Rele	ease Minor Release	Volume of Release < 15 bbls Volume Recovered None									
Source of Release Oil and Produced Water					Date and Hour of Occurrence Date and Hour of Discovery 06/06/16						
Was Immedi	iate Notice Given?	If YES, To Whom?									
Yes □ No ☒ Not Required ☐											15.5 162
By Whom? Kyle Berend Was a Watercourse Reached?					Date and Hour 06/09/16 @ 8:00 a.m. If YES, Volume Impacting the Watercourse.						
was a watercourse reaction: ☐ Yes 🖾 No					. 11 155, volume impacting the watercourse.						
If a Waterco	urse was Impacted, Desc	ribe Fully	.	:							
I a watered	disc was impacted, Desi	nioc i uny.	1.7) · · ·		•		•			
						•					, 44 5
Describe Cause of Problem and Remedial Action Taken.*											
Produced fluids have leaked from the storage tanks. Most of the contamination looks to be historic.											
Produced no	nus nave ieakeu nom m	e storage tai	iks. Wost of the	Comaini	Halloll IQUKS (o be instoric.					
Describe Are	ea Affected and Cleanup	Action Tal	cen.*			•	•				
The release h	had breached the dike an	d had run s	everal yards outsi	de the c	ontainment ar	rea. We will dig	up and r	replaced co.	ntaminated a	rea alo	ng with
improving th	ne dike.	~ A~. A	les Roque		1						
	X 2166	Samp	res 100 qui	EO.							
I hereby cert	ify that the information	given above	is true and comp	lete to t	he best of my	knowledge and t	ındersta	ind that pur	suant to NM	OCD r	ules and
regulations a	all operators are required n or the environment. The	to report a	nd/or file certain	release n	otifications a	nd perform correct	ctive act	tions for rel	leases which	may er	ndanger
should their	operations have failed to	adequately	investigate and i	emediat	te contaminati	ion that pose a thi	reat to g	round wate	r, surface wa	iter, hu	man health
or the enviro	nment. In addition, NM	IOCD accer	tance of a C-141	report d	loes not reliev	e the operator of	respons	sibility for o	compliance v	vith any	y other
federal, state	, or local laws and/or re	gulations.	,	· 		OH CON	CEDY	/ A TION	DIVIGIO	NN T	
1 20 1 1					OIL CONSERVATION DIVISION						
Signature:					Signed By Miles Kann						
Britand Name Wells Round					Approved by Environmental Specialist.						
Printed Nam	e: Kyle Berend			* +		1,111111			.\ /.	1	
Title: Reg	ulatory Analyst	Approval Date: UIIII Expiration Date: NA									
E-mail Add	peer Charand Ahheall	com			Conditions o	f Approval:				_	
E-mail Addr	ess: kberend@bbsoil.	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines									
	06/16	Pho	ne: (940)549-0	780		REMEDIATIO			NO		
' Attach Add	itional Sheets If Nece	ssary			LATER T	~	[14]	[[]	20	D.7	5738