

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUN 13 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.  
**RECEIVED**

## Release Notification and Corrective Action

NAB16161636453

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Matador Resources <u>228437</u>	Contact Catherine Green
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Janie Conner 13 24S 28E RB #221H	Facility Type Oil well

Surface Owner Private	Mineral Owner	API No. 30-015-43756
-----------------------	---------------	----------------------

## LOCATION OF RELEASE

Unit Letter A	Section 14	Township 24S	Range 28E	Feet from the 379	North/South Line N	Feet from the 330	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude 32.2238661 Longitude -104.0500431

## NATURE OF RELEASE

Type of Release Oil Based Mud	Volume of Release 13 bbls	Volume Recovered 13bbls
Source of Release Frac tank hose	Date and Hour of Occurrence 6/12/16 12:15am	Date and Hour of Discovery 6/12/16 12:15am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Casey Snow	
By Whom? Martin Boquet	Date and Hour 6/12/16 3pm.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Hose separated at connection. Procedure was halted. Hose was crimped.

Describe Area Affected and Cleanup Action Taken.\*

Material was vacuumed up on location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: Catherine Green

Printed Name: Catherine Green

Title: Regulatory Analyst

E-mail Address: cgreen@matadorresources.com

Date: June 13, 2016 Phone: 575-623-6601

Signed By: [Signature]  
Approved by Environmental Specialist

Approval Date: 6/14/16 Expiration Date: N/A

Conditions of Approval:  
Remediation per O.C.D. Rules & Guidelines ☒

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 7/14/16 2RP-3139

\* Attach Additional Sheets If Necessary